

TITLE	SCALE	REV.	INTERACTIVE MODEL
Sill and mullion rebuild Terra cotta, extruded	None	02/01/21	https://imisketchupmodels.blogspot.com/2020/11/100300433-sill-and-mullion-rebuild.htm

KEY NOTES

- $\langle 01 \rangle$ (E) Masonry backup, multiwythe construction
- $\langle 11 \rangle$ Architectural terra cotta, extruded
- $\langle 21 \rangle$ Mortar
- $\langle 38 \rangle$ Stainless steel strap and pin anchor
- (39) Stainless steel split tail anchor
- $\langle 51 \rangle$ Flashing system with end dams as réquired
- $\langle 52 \rangle$ Termination bar with continuous sealant
- 54 Stainless steel drip edge; seal and adhere to substrate $\langle 59 \rangle$ Weep vent
- $\langle 60 \rangle$ Weep hole at underside of each overhanging TC unit
- $\langle 72 \rangle$ Sealant and backer rod
- $\langle 74 \rangle$ Sealant or lead T-caps at all horizontal skywardfacing joints
- $\langle 75 \rangle$ Plastic setting shims as required
- $\langle 81 \rangle$ (E) Window assembly
- $\langle 94 \rangle$ (E) Structural steel treated with corrosion-inhibiting coating

GENERAL NOTES

This drawing references Sill and Mullion - Original Plate 32.

- Where anchors penetrate flashing, seal with compatible sealant.
- Anchors to be located at end of TC units; shown at cut unit for clarity.

DELIMITATION

This detail exhibits rebuild strategies with extruded architectural terra cotta (TC). Other options may be appropriate. It is best to consult a professional team of engineers, architects, and architectural conservators when crafting a repair or rebuild scenario for historic architectural TC.

CONSIDERATIONS

- Architect/engineer to verify condition and soundness of existing (E) masonry backup. Perform testing as necessary.
- Rebuild or replace backup as necessary.
- Replacing anchors requires performing anchorage pull-testing.
- Accessible existing sound steel that is to remain, requires cleaning and coating with a corrosion inhibitor.
- Corroded steel to be evaluated and painted, repaired, or replaced with stainless steel based on condition
- Original TC units are to be replaced in-kind or removed, repaired, and reinstalled and not filled.
- Install new TC units not filled.
- Weep holes in units must be kept clear and free of mortar and debris to prevent trapping of moisture after installation.
- Design considerations include: Tolerances

 - Shims
 - Shoring Modifications to units
 - (E) Anchor removal

KEYWORDS

Terra cotta, Rebuild, Extruded, Sill, Mullion, Brick, Restoration, Anchor, Repair, Window, Flashing, 10.030.0433





html

SHEET NO. 10.030.0433



Note: This Terra Cotta Detail is a modern rendering of the original detail shown in Plate 32 of Terra Cotta Standard Construction, published by the National Terra Cotta Society in 1914.

TITLE

Sill and Mullion - Original Plate 32



KEYWORDS

REV.

09/10/20

<u>Section</u>

SCALE

None

Terra Cotta, Hand Pressed, Sill, Mullion, Brick, Restoration, Anchor, Repair, Window, Flashing, Original Plate 32, 10.030.0431

SHEET NO.

10.030.0431

© 2020 International Masonry Institute www.imiweb.org

(01) Masonry backup, multi-

KEY NOTES

wythe construction

INTERNATIONAL

MASONRY

- Architectural terra $\langle 11 \rangle$
- cotta, hand pressed

 $\left< \frac{21}{2} \right>$ Mortar

 $\langle 32 \rangle$ Steel Z anchor

 $\langle 33 \rangle$ Steel plate

 $\langle 37 \rangle$ Steel rod

- $\langle 54 \rangle$ Steel hook anchor
- $\langle 81 \rangle$ Window assembly

(94) Steel angle

98) Steel T-bar