



## MASONRY WALL REINFORCING ELEVATION

NOT TO SCALE

### NOTES:

1. LAP REINFORCING BARS AS INDICATED IN THE MASONRY NOTES ON S\_\_\_\_\_.
2. PROVIDE HORIZONTAL JOINT REINFORCING AT 16"OC AND AT TOP TWO COURSES UNLESS NOTED OTHERWISE.
3. AT INTERIOR PARTITIONS, WHERE NO FOUNDATION WALL IS PRESENT, PROVIDE (1)#4 CONTINUOUS IN SLAB (TYPICAL).
4. AT INTERIOR, NON-LOAD BEARING PARTITIONS, TOP OF PARTITION SHALL BE 1" MINIMUM BELOW FRAMING MEMBERS, SLABS, PLANK, OR DECK TO ALLOW FOR DEFLECTION OF STRUCTURE ABOVE. BRACE TOP OF PARTITION AS SHOWN IN \_\_\_\_\_.
5. IF HORIZONTAL REINFORCEMENT IS USED, USE LADDER TYPE.



### RYAN-BIGGS ASSOCIATES, P.C.

291 River Street p 518 272.6266  
 Troy, NY 12180 f 518 272.4467  
 www.ryanbiggs.com

SUBJECT: WALL REINFORCING

PAGE: 12

JOB NO.: 9252

DATE: 8/22/08

PROJECT: LOAD BEARING MASONRY

BY: DTB