


OPTION 1
RAKE BACK MORTAR AND
APPLY SEALANT JOINT



OPTION 2
SEALANT AND
BACKER ROD



INCORRECT
TOOLED MORTAR JOINT

MASONRY COPING JOINTS

DETAIL 01.030.0811

REV. 11/04/08

International Masonry Institute



800-IMI-0988 www.imiweb.org

© 2011 INTERNATIONAL MASONRY INSTITUTE