



NOTE: MOISTURE MEMBRANE AND/OR CRACK SUPPRESSION MEMBRANE MAY BE REQUIRED; NOT SHOWN

RUSTIC TERRAZZO

SYSTEM OVERVIEW

DETAIL 07.130.0511

REV. 04/07/11

International Masonry Institute



800-IMI-0988 www.imiweb.org

© 2011 INTERNATIONAL MASONRY INSTITUTE