



# REINFORCEMENT PLACEMENT TOLERANCE

DIAGRAM 02.410.0122

REV. 02/24/09

International Masonry Institute



800-IMI-0988 [www.imiweb.org](http://www.imiweb.org)

© 2011 INTERNATIONAL MASONRY INSTITUTE