



NOTE: MOISTURE
MEMBRANE AND/OR CRACK
SUPPRESSION MEMBRANE
MAY BE REQUIRED; NOT
SHOWN

BONDED TERRAZZO SYSTEM OVERVIEW

DETAIL 07.130.0611

REV. 04/07/11

International Masonry Institute



800-IMI-0988 www.imiweb.org

© 2011 INTERNATIONAL MASONRY INSTITUTE