



PLANK AT BEARING WALL INTERIOR, TOP OF WALL

DETAIL 02.120.0852

REV. 11/25/08

International Masonry Institute



800-IMI-0988 www.imiweb.org

© 2011 INTERNATIONAL MASONRY INSTITUTE